## IOTA WIRING FOR 1AMP STEPPER MOTORS: IOTA CONTROLLER



## 2 Motor Drivers

24V, 1A, drivers, microstepping for smooth operation.

Drives IOTA slider, Dragonframe focus motor, and most other small bipolar step motors.

Using Dragonframe's exciting Arc Motion Control workspace, you can fully animate two stepper motors (1 amp) for moving your camera or even animate objects in your shot.

Connect to IOTA Controller with a Male 5pin XLR

## **Stepper Motor Connections:**

- 1. A
- 2. A-
- 3 Gnd
- 4. B
- 5. B-





